

Re-Build Existing Pumps: Hydrostal Brand, Model: H5K-S-HEUC4

***Please Note: This parts list is for one pump. We have two pumps that need to be rebuilt, so the items on this list will need to be duplicated in your bid.**

Item Description, Qty

-1947437 1947437, SEALING RING 13X18X2MM COPPER Qty 3
-6355694 SEALING RING 21/26X1.5MM COPPER Qty 2
-6290799 OIL SEAL NITRILE Qty 1
-1877112 O-RING NITRILE Qty 1
-1877112 O-RING NITRILE Qty 1
-6317017 6317017, O-RING NITRILE Qty 2
-6559728 O-RING NITRILE Qty1
-5494030 ORing Nitrile Qty 1
-5190675 5190675, O-RING NITRILE Qty 1
-3893380 3893380, O-RING NITRILE Qty 1
-6115884 6115884, MECHANICAL SEAL X 3" SC/TC NITRILE STAINLESS STEEL HOUSED MULTI SPRING SEAL Qty 1
-7941560 MECHANICAL SEAL F 3 3/4" 95MM SC/C NITRILE RUBBER BELLOW SINGLE SPRING SEAL Qty1
-8278841 RING ROLLED MOTOR SIZE U, 6X518MM STEEL A570 Qty 1
-9386906 BEARING CAP EX MOTOR SIZE U CAST IRON A48CL30 Qty 1
-5433475 DISK MOTOR SIDE MOTOR 6 STEEL A570 Qty 1
-1326256 GREASE RETAINING DISC MOTOR SIZE 6 90/60.5X2MM STEEL A570 Qty 1
-9886697 GREASE RETAINING DISC MOTOR SIZE 6 90/65X2MM STEEL A570 Qty 1
-1215560 SNAP RING (SEEGER) A77 STAINLESS STEEL Qty 1
-8033389 SANP RING (SEEGER) A95, SPRING STEEL BLACK Qty 1
-8333235 SNAP RING (SEEGER) I90 Qty 1
-4577815 SPACER RING 70/90X3.5MM SPRING STEEL AISI9262 Qty 1
-9564421 LOCKNUT FOR SHAFT M100X2MM MOTOR SIZE U STEEL AISI5210 In stock Qty 1
-6290799 OIL SEAL NITRILE Qty 1
-7762045 BEARING TEMPERATURE PROBE 120 DEGREE, M4 Qty1
-9691043 FLOAT SWITCH TYP G 1/8 NC CABLE 0.2M Qty1
-3255674 MOISTURE PROBE INTERNAL SHORT Qty 1
-5241617 THERMISTOR Qty 3
-4210997 SNAP RING (SEEGER) I80 Qty 1
-8LW-7220 8LW-7220BGUOM Qty 1
-2083068 2083068, ANGULAR CONTACT BALL BEARING Qty 2
-VOLUTE CASING MATERIAL: CAST IRON A45CL30
-IMPELLER MATERIAL: HI-CHROME A532-III-A
-LINER MATERIAL: HI-CHROME A532-III-A
-SUCTION CASING/COVER MATERIAL: CAST IRON A45CL30
-WEAR RING MATERIAL: N/A
-IMPELLER FLANGE MATERIAL: DUCTILE IRON A536-80-55-06

Field Service Pump Motor Repair.

Includes:

Motor rewind, enhanced insulation, mechanical rebuild, AEGIS shaft grounding ring and ceramic coating on the upper bearing housing to bring motor to appropriate VFD standards.

Model: H5K-S-HEUC4

Serial #: 186885

Please include Freight and Shipping in your bid

Sealed bids will be accepted until February 8, 2018 @ 2:00pm.

Proposals **MUST** be hand-delivered, mailed, or delivered by courier. Facsimile and/or electronic submissions will **NOT** be accepted, and will be deemed non-responsive. **Envelopes must be clearly marked on the outside "Pump Motor Repairs/Rebuild"**.

Proposals received after the date or time stated will not be considered; postmarks will be not accepted as proof of submission. Proposals received prior to the date or time stated will be held until time of opening.

Bids must be received & stamped on or before the Bid due date and time at this location:

Public Works Department
525 W. Cota Street
Shelton, WA 98584